Tuboscope NOV	Pup Joint Inspection Report	**Customer:-** Woodside Mauritania **WO:-** TBA **PO:-** 7500064424 **Date:-** 23-10-07

Size	6 5/8”	Wall	0.598”	Grade	G-105	Connection	FMC-69	Tool joint OD	8 ½”	Pin ID	5 1/4”		
Inspection Specification Used:-	FMC Doc No PSM-0000022268 Rev: C (Section-6.0 Rev-01)						√	Grant Prideco (Field Insp Procedure for Used XT & XTM) Rev-08					√

Jt No	Serial Number	Pin Cond	Box Cond	Pin OD	Box OD	Pin TS	Box TS	Pin Nose Dia	Counterbore Dia	Pin Lgth	Box Lgth	COMMENTS
1	GP145515-1	ACC	ACC	8 ½”	8 ½”	35 5/8”	17 5/8”	ACC	ACC	7.807”	7.818”	15’
2	GP145518-1	ACC	ACC	8 ½”	8 ½”	35 5/8”	17 ½”	ACC	ACC	7.809”	7.818”	15’
3	GP145519-1	ACC	ACC	8 ½”	8 ½”	15 5/8”	9 1/8”	ACC	ACC	7.807”	7.820”	10’
4	GP145522-1	ACC	ACC	8 ½”	8 ½”	35 7/8”	17 5/8”	ACC	ACC	7.809”	7.818”	15’
5	GP145509-1	ACC	ACC	8 ½”	8 ½”	35 3/8”	17 ½”	ACC	ACC	7.808”	7.818”	20’
6	GP145500-1	ACC	ACC	8 ½”	8 ½”	35 ½”	17 ½”	ACC	ACC	7.809”	7.819”	20’
7	GP145512-1	ACC	ACC	8 ½”	8 ½”	35 7/8”	17 ½”	ACC	ACC	7.808”	7.818”	20’
8	GP145525-2	ACC	ACC	8 ½”	8 ½”	15 1/8”	11”	ACC	ACC	7.808”	7.820”	5’
9	GP145519-2	ACC	ACC	8 ½”	8 ½”	15”	11”	ACC	ACC	7.807”	7.818”	5’
10	GP145504-2	ACC	ACC	8 ½”	8 ½”	15 ½”	11 ½”	ACC	ACC	7.804”	7.820”	5’
11	GP145513-1	/	ACC	8 ½”	8 ½”	15 ½”	11 ½”	/	ACC	7.807”	7.819”	10’ (Pin attached to tool)
12	GP145525-1	/	ACC	8 ½”	8 ½”	15 ¾”	11 ½”	/	ACC	7.806”	7.818”	10’ (Pin attached to tool)

LEGEND

Connection	TD = Thread damage	SD = Seal damage	Corr = Corroded	ACC = Acceptable	IC=Internal coating	Classified as per NS-2 = A - E	N=None	Classified as per DS-1 = 1 - 4
Body / Tool joint	P = Premium Class	R = Reject	IP = Internal Pitting	EP = External Pitting	SAD = Slip Area Damage	CRK = Crack	US = Undersize Tool Joint OD	